



*East Colonnade, East Elevation. [JGWA, 2006]*



*East Colonnade, East Elevation. The marble entablature and soffit have been soiled and stained by rainwater run-off, originating in the terrace construction above. [JGWA, 2006]*