



*Rotunda, Roof. [JGWA, 2006]*



*Rotunda, Roof. The painted finish on the terne-coated sheet metal roofing of the dome is crazed and rust stained; this condition is pronounced on the north elevation. [JGWA, 2006]*