



*Rotunda, Roof. Inadequate attempts have been made to cover areas of exposed sheet metal on the steps at the base of the dome with smeared sealant. The sealant is supporting the growth of algae.[JGWA, 2006]*



*Rotunda, Roof. The painted finish on the terne-coated roofing of the dome is crazed and peeling; the underlying sheet metal is rusting through. [JGWA, 2006]*