



*Men's Toilet Room (T113),
looking northeast. [JGWA,
2006]*



*The plaster wall and ceiling
surfaces in the northeast
corner of the Men's Toilet
Room (T113) are badly
blistered. The plaster is
friable, and the painted finish
is peeling as a result of water
infiltration. [JGWA, 2006]*