



*Elevator Machine Room (110A) below the North Portico. [JGWA, 2006]*



*The exposed steel beam supporting the sloped concrete ceiling of Elevator Machine Room (110A) has significant surface rust. The rust is more advanced at the beam's bearing point in the north wall. Galvanized sheet metal and acrylic glazing have been installed above the elevator machinery to protect the equipment from water infiltration occurring in the north portico steps above. [JGWA, 2006]*