



*Generations of temporary shoring have been introduced in the Mechanical Room beneath the north portico to support the ceiling and terrace construction above. [JGWA, 2006]*



*Significant problems with water infiltration in the Mechanical Room beneath the north portico have lead to advanced deterioration of equipment and fixtures. [JGWA, 2006]*