



*The floor finish in the President's Reception Room (Upper West Oval Room 201) is discolored as a result of UV degradation. This was made apparent by the removal of the large oval rug that was located in the center of the room. [JGWA, 2006]*



*Floor sanding in the Center Hall (C202/C203) was continued through the east entry of the President's Reception Room (Upper West Oval Room 201). This refinishing work and the perimeter abrasion from a large oval rug have caused discoloration and uneven wear in the heart pine flooring. [JGWA, 2006]*