



*Several of the perimeter spotlights at the base of the dome are not illuminated. Others have been removed or displaced by the installation of HVAC grilles. [JGWA, 2006]*

*Metal brackets were retrofitted beneath the high temperature spotlights at the base of the dome to prevent the fixtures from dropping and charring the plywood shelf on which they are mounted. [JGWA, 2006]*