



*The fluorescent strip lighting fixtures at the base of the dome were removed in December 2006 as part of the mold remediation project. Exposed conductors protruding from conduit remain; these conductors may present an electrical shock hazard. [JGWA, 2006 (top), 2007 (bottom)]*