



*Northeast Wing, North Elevation. [JGWA, 2006]*



*Northeast Wing, North Elevation. The painted surfaces have chalked and stained the brickwork. There is dark biological staining on the brick near the rusted areaway grates. [JGWA, 2006]*