



*West Colonnade, West Elevation.[JGWA, 2006]*



*West Colonnade, West Elevation. There are lime-run (calcium carbonate) deposits at the vertical joints in the marble entablature, and rust colored staining on the architrave. This deterioration has resulted from water percolating through the terrace construction above. [JGWA, 2006]*