



*West Terrace. Debris from the magnolia trees accumulates on the terrace. [JGWA, 2006]*



*West Terrace. There is vivid orange “staining” along the bottom rails of the marble balustrades; this appears to be subsurface biological growth. [JGWA, 2006]*