



*The emergency exit door (left) and floor slab (above) of the Northwest Fire Stair (C117) are dirty and covered with cob webs. The illuminated exit sign is not working. [JGWA, 2006]*